

贵州昊华工程技术有限公司职业卫生技术报告公开信息

用人单位 (建设单位) 名称	贵州恒轩新能源 材料有限公司	用人单位 (建设单位) 地址	贵州省福泉 市龙昌经济 开发区	用人单位 (建 设单位) 联系 人	蹇云
技术服务项 目名称	贵州恒轩新能源 材料有限公司	技术服务类 型	职业病危害 因素定期监 测	报告编号	GZHHZW-检- 065 (2026)
技术服务项 目组人员	赵彪、王成、王鑫、罗蔚			出具报告时间	2026. 09. 20
现场调查人 员	赵彪、王成	现场调查时 间	2026.08.07	建设单位 (用 人单位) 陪同 人	蹇云
现场采样及 检测人员	赵彪、王成	现场采样时 间	2026.08.13	建设单位 (用 人单位) 陪同 人	蹇云
现场调查合 影照片	 A photograph showing three individuals standing on the steps of a modern building with large glass windows. The date '2026.08.07' is visible in the bottom right corner of the photo.				
现场采样及 检测照片	    Four photographs documenting the sampling and detection process. The top-left photo shows an industrial interior with large tanks and equipment, dated 2026.08.13. The top-right photo shows a worker in a white protective suit and red helmet operating machinery, dated 2026.08.13. The bottom-left photo shows a large industrial storage tank with sampling equipment, dated 2026.08.13. The bottom-right photo shows a worker in a white protective suit and red helmet standing near a large bag, dated 2026.08.13.				